AD

AD-A188 767

# Report



United States Army Belvoir Research, Development & Engineering Center Fort Belvoir, Virginia 22060-5606

Report 2457



# **Rust Converters**

Dario A. Emeric, Bryan Westich, Authored By: and Richard C. McNeil

Report Date: November 1987

Approved for public release; distribution unlimited.

Destroy this report when it is no longer needed. Do not return it to the originator.

The citation in this report of trade names of commercially available products does not constitute official endorsement or approval of the use of such products.

ECURIT	ľΥ	CLAS	SIFICA	TION	OF	THIS	PAG	ξ

REPORT DOCUMENTATION PAGE					Form Approved OMB No 0704-0188 Exp. Date: Jun 30, 1986	
1a REPORT SECURITY CLASSIFICATION Unclassified	16 RESTRICTIVE MARKINGS					
2a. SECURITY CLASSIFICATION AUTHORITY	None 3 DISTRIBUTION	/AVAILABILITY OF	REPORT			
NA 2b. DECLASSIFICATION / DOWNGRADING SCHEDU	Approved for public release;					
NA	LE	distribution unlimited.				
4 PERFORMING ORGANIZATION REPORT NUMBER	R(S)	5. MONITORING ORGANIZATION REPORT NUMBER(S)				
2457	NA .					
60 NAME OF PERFORMING ORGANIZATION	6b OFFICE SYMBOL (If applicable)	7a NAME OF MONITORING ORGANIZATION				
Chemistry Research Group Materials, Fuels & Lubricants		l NA				
6c. ADDRESS (City, State, and ZIP Code)	<u> </u>	76 ADDRESS (Ci	ty, State, and ZIP	Code)		
Belvoir RD&E Center Fort Belvoir, VA 22060-5606		NA.				
Total Belvoit, VR 22000-5000		NA NA				
Ba. NAME OF FUNDING SPONSORING	Bb. OFFICE SYMBOL	9. PROCUREMEN	T INSTRUMENT ID	ENTIFICAT	ION NUMBER	
ORGANIZATION Same	(If applicable)	NA.				
8c. ADDRESS (City, State, and ZIP Code)	<u> </u>	10 SOURCE OF	FUNDING NUMBER	is .		
		PROGRAM ELEMENT NO	PROJECT NO	TASK NO	WORK UNIT ACCESSION NO	
			1			
11. TITLE (Include Security Classification)						
Rust Converters (Unclassified	١					
12. PERSONAL AUTHOR(S)	<u></u>		<del></del>			
Dario A. Emeric, Bryan Westic		<del></del>		Ti-	0.61.60	
13a. TYPE OF REPORT 13b. TIME C Final FROM 10	/1/85 TO 9/30/87	14 DATE OF REPO		כון נענט	PAGE COUNT	
16. SUPPLEMENTARY NOTATION						
16. SUPPLEMENTARY NOTATION	/	HOVEHIDEL 1				
16. SUPPLEMENTARY NOTATION		NOVEMBEL 1			· · · · · · · · · · · · · · · · · · ·	
17 COSATI CODES	18. SUBJEÇT/JERMS			Lidentify	·	
		Continue on revers	e if necessary and	l identify	·	
17 COSATI CODES			e if necessary and	dentify	·	
17 COSATI CODES	rust conver	Continue on revers	e if necessary and	l identify	·	
17 COSATI CODES FELD GROUP SUB-GROUP  19. ABSTRACT (Continue on reverse if necessary	rust conver corrosion and identify by block in	Continue on revers tersjinhibit	cors)	· · · · · · · · · · · · · · · · · · ·	by plock number)	
17 COSATI CODES FELD GROUP SUB-GROUP	rust conver corrosion and identify by block of the corrosion, the	Continue on reversiters inhibit	ors) Research Gr	oup, M	by block number)	
17 COSATI CODES  SUB-GROUP  19 ABSTRACT (Continue on reverse if necessary  To supplement the war again  Fuels and Lubricants Labora  Center, is currently develo	rust conver corrosion and identify by block of st corrosion, the tory, Belvoir Reping a rust conv	continue on reversiters inhibit commer.  The Chemistry search. Development of the commer is a commer of the comment of the com	Research Grelopment and	oup, M Engine tary a	aterials, eering pplica-	
17 COSATI CODES  19 ABSTRACT (Continue on reverse if necessary  To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial sc	rust conver corrosion and identify by block of st corrosion, the tory, Belvoir Reping a rust convergence of the convergence of	continue on reversiters inhibit (mmber)  The Chemistry (search, Development of the best of the continue on reverse of the best	Research Grelopment and ole for mili	oup, M Engind tary a availa	aterials, eering pplica- ble rust	
17 COSATI CODES  19 ABSTRACT (Continue on reverse if necessary  To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial sc converters were evaluated o steel and galvanized panels	rust conver corrosion and identify by block of st corrosion, the tory, Belvoir Reping a rust convergening process, wer field and law. Following the	continue on reversiters inhibit (mber)  The Chemistry (search, Deverter suitable the best continue of the best continue of the laboratory preserved in the laboratory pres	Research Grelopment and ole for miliommerically e-corroded catory and fi	oup, M. Engine tary a availa old ro eld ex	aterials, eering pplica- ble rust lled amination,	
19. ABSTRACT (Continue on reverse if necessary To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial so converters were evaluated o steel and galvanized panels it was determined that curr	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the converged and the corrosion are field and the corrosion and identify by block of the corrosion and identify by block of the corrosion, the corrosion are field and the cor	ters inhibit  te	Research Grelopment and ple for milipmerically e-corroded catory and fiters actuall	oup, M. Engine tary a availa old ro eld ex	aterials, eering pplica- ble rust lled amination,	
17 COSATI CODES  19 ABSTRACT (Continue on reverse if necessary  To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial sc converters were evaluated o steel and galvanized panels	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the converged and the corrosion are field and the corrosion and identify by block of the corrosion and identify by block of the corrosion and identify by block of the corrosion, the corrosion are field and the corresponding are field and the corr	ters inhibit  te	Research Grelopment and ple for milipmerically e-corroded catory and fiters actuall	oup, M. Engine tary a availa old ro eld ex	aterials, eering pplica- ble rust lled amination,	
19. ABSTRACT (Continue on reverse if necessary To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial so converters were evaluated o steel and galvanized panels it was determined that curr	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the converged and the corrosion are field and the corrosion and identify by block of the corrosion and identify by block of the corrosion and identify by block of the corrosion, the corrosion are field and the corresponding are field and the corr	ters inhibit  te	Research Grelopment and ple for milipmerically e-corroded catory and fiters actuall	oup, M. Engine tary a availa old ro eld ex	aterials, eering pplica- ble rust lled amination,	
19. ABSTRACT (Continue on reverse if necessary To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial so converters were evaluated o steel and galvanized panels it was determined that curr	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the converged are the converged and the corrosion are field and the corrosion and identify by block of the corrosion and identify by block of the corrosion, the corrosion and identify by block of the corrosion, the corrosion are field and the corresponding are field and the corresp	ters inhibit  te	Research Grelopment and ple for milipmerically e-corroded catory and fiters actuall	oup, M. Engine tary a availa old ro eld ex	aterials, eering pplica- ble rust lled amination,	
19. ABSTRACT (Continue on reverse if necessary To supplement the war again Fuels and Lubricants Labora Center, is currently develo tions. After an initial so converters were evaluated o steel and galvanized panels it was determined that curr	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the converged are the converged and the corrosion are field and the corrosion and identify by block of the corrosion and identify by block of the corrosion, the corrosion and identify by block of the corrosion, the corrosion are field and the corresponding are field and the corresp	ters inhibit (continue on reversiters) inhibit (continue) (continu	Research Grelopment and ole for milionmerically e-corroded catory and fitters actually	oup, M. Engine tary a availa old ro eld ex y acce	aterials, eering pplica- ble rust lled amination,	
17 COSATI CODES    ELD   GROUP   SUB-GROUP    19 ABSTRACT (Continue on reverse if necessary   To supplement the war again. Fuels and Lubricants Labora Center, is currently develotions. After an initial sc converters were evaluated of steel and galvanized panels it was determined that curr corrosion after a period of	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the corrosion are field and the corrosion and the corrosion are field and the corrosion are field and the corrosion are fiel	ters inhibit  te	Research Grelopment and ole for milionmerically e-corroded catory and ficers actually it.	oup, M. Engine tary a availa old ro eld ex y acce	aterials, eering pplica- ble rust lled amination,	
17 COSATI CODES    ELD   GROUP   SUB-GROUP	rust convercorrosion and identify by block of the corrosion, the corrosion, the corrosion are converged and the corrosion are field and the corrosion and the corrosion are field and the corrosion are field and the corrosion are fiel	ters inhibit  te	Research Grelopment and ole for milionmerically e-corroded catory and ficers actually it.	oup, M. Engine tary a availa old ro eld ex y acce	aterials, eering pplica- ble rust lled amination, lerated	

DD FORM 1473, 84 MAR

83 APR edition may be used until exhausted All other editions are obsolete

SECURITY CLASSIFICATION OF THIS PAGE

# **PREFACE**

In 1980, an Inspector General's report indicated that 40 percent of fielded tactical vehicles (such as trucks, jeeps, trailers) belonging to the 25th Infantry Division, Western Command (WESTCOM), were inoperable mainly due to corrosion. At the request of and in conjunction with the Tank-Automotive Command (TACOM), coatings and corrosion specialists from Belvoir Research, Development, and Engineering (RD&E) Center's Materials, Fuels, and Lubricants Laboratory visited the 25th Infantry Division to survey the situation. Based on recommendations and technical guidance, WESTCOM undertook a corrosion repair and rustproofing program.

To supplement the war against corrosion, The Chemistry Research Group of the Materials, Fuels, and Lubricants Laboratory is currently undertaking a research and development effort to develop a rust converter suitable for military applications. The studies include determining rust inhibitor compatibility with MIL-C-62218, "Corrosion preventative compounds, cold-application (for new and fielded motor vehicles and trailers)."

In the evaluations contained in this report, rust converters/inhibitors were used to passivate a pre-corroded substrate. Phosphoric acid and tannic acid based rust converters chemically change the composition of the ferrous oxide to a ferric phosphate and a ferric tannate, respectively, forming an adherent substrate which may then be coated with a bituminous coating. The ensuing experiments compare the rust inhibitors' conversion of both field and laboratory pre-corrosion. The project's goal was to use laboratory and field evaluations to develop a rust converter that would withstand military environments.

The following test methods and standards were used in the rust converte: testing:

American Society for Testing and Materials (ASTM) B 117, "Standard method of salt spray (fog) testing"

ASTM D 610, "Standard method of evaluating degree of rusting of painted steel surfaces"

ASTM D 714, "Standard method of evaluating degree of blistering of paints"

ASTM D 1654, "Standard method for evaluation of painted or coated specimens subjected to corrosive environments"

ASTM D 2247, "Standard method for testing coated metal specimens at 100% relative humidity"

ASTM D 3170, "Standard test method for chip resistance of coatings"

Federal Test Method Standard (FTMS) 6226, "Impact resistance (reverse)."

Steel Structures Painting Council, Surface Preparation, Specification No. 2 (SSPC-SP2), "Hand Tool Cleaning"

Tests performed on the rust converters used the following equipment:

Harshaw Salt Fog Cabinet, Model #22, Harshaw Chemical Company

Humidity Chamber, Model #QCT - ADO, Q-Panel Company

Gravelometer, Model #QGR, Q-Panel Company

Cold-Temperature Chamber (cold box), Model # TM-35, B-M-A Inc.

Coatings Film Knife. Model #201, Pacific Scientific


G.E. Impact Tester, fabricated at the Belvoir Research, Development, and Engineering Center according to FTMS 6226

#### The following two panels were used in testing:

Cold Rolled Steel Q-Panels, R-Type, 0.023" thickness, dull matte finish, 4" x 12" and 3" x 6" size, Q-Panel Company, 26200 First Street, Cleveland, OH 44145

Galvanized Panels, minimum spangle T.R., heavy duty galvanized, clean treatment, 4" x 12" x 22" gauge; G-90, Parker Chemical Company, 32100 Stevenson Highway, Madison Heights, MI 49256





# **CONTENTS**

Sect	tion Page
I	Panel Preparation 1
II	Cyclic Gravelometer/Salt Spray 2
Ш	Humidity5
IV	Reverse Impact Resistance 8
v	Florida Testing11
VI	Field Exposure
VII	Conclusions and Recommendations
Figu	ires
1	Rack in the Salt Spray Chamber
2	Cyclic Gravelometer/Salt Spray—Laboratory Pre-Corrosion 3
3	Cyclic Gravelometer/Salt Spray—Field Pre-Corrosion 4
4	Humidity—Laboratory Pre-Corrosion
5	Humidity—Field Pre-Corrosion
6	Impact Weight 8
7	Reverse Impact Resistance—Laboratory Pre-Corrosion 9
8	Reverse Impact Resistance—Field Pre-Corrosion
9	Florida Testing—Laboratory Pre-Corrosion
10	Florida Testing—Field Pre-Corrosion

# SECTION I. PANEL PREPARATION

Pre-corrosion of the panels was the first step in the preparation process. A corroded substrate must be present for the rust converter to react and form a passive layer preventing further corrosion. The panels were corroded in two different ways—in the laboratory and in the field. Laboratory pre-corrosion was performed in the Harshaw salt fog cabinets according to ASTM B 117, "Standard method of salt spray (fog) testing." Mild and severe depths of pre-corrosion were created for testing:

	Mild pre-corrosion	Severe pre-corrosion
Cold rolled steel	24 hours	120 hours
Galvanized (G-90)	74 hours	144 hours

In the field, the pre-corrosion was performed by WESTCOM in Hawaii and Sub-Tropical Testing Service in Miami, Florida. The panels were oriented at a 45° angle from the horizontal facing south for a period of 1 year.

After the pre-corrosion process, the loose corrosion was removed according to Steel Structures Painting Council, Surface Preparation Specification No. 2 (SSPC-SP2). "Hand Tool Cleaning." This step created an adherent surface for the rust converter to passivate, rather than converting a corrosion nodule which could easily be knocked off.

The rust converters were then applied according to the manufacturers' specifications. To establish uniformity, the following process was developed:

- Step 1. Wet panel.
- Step 2. Tilt panel to allow excess water—such as puddles—to run off.
- Step 3. Brush on first coat of rust converter.
- Step 4. Let panel dry for no less than 12 hours.
- Step 5. Rinse panel and repeat step 2.
- Step 6. Brush on second coat of rust converter.
- Step 7. Let panel dry for no less than 12 hours.

The panels were then topcoated with Tectyl 517 (MIL-C-62218 bituminous compound). The topcoat was drawn down to an 11 mil wet film thickness (WFT) and allowed to cure for 7 days to a 5 mil dry film thickness (DFT).

Unless otherwise specified, the following rust converters were evaluated in each test:

Commercial #1 (phosphoric acid based)

Commercial #2 (tannic acid based)

Commercial #3 (tannic acid based with latex)

Commercial #4 (tannic acid based with latex)

Pre-corroded panels converted with rust converter and topcoated with Tectyl 517 were evaluated along with Tectyl 517 directly over the pre-corroded panels as a control.

#### SECTION II. CYCLIC GRAVELOMETER/SALT SPRAY

Impact by the gravelometer was performed in accordance with ASTM D 3170, "Standard test method for chip resistance of coatings." After the panels were prepared and cured, they were placed in the cold temperature chamber and cooled to -30°F for 2 hours prior to testing. This temperature was 10° colder than the actual test temperature of -20°F. As specified in ASTM D 3170, the 10-second warm up period accounted for the time it took to remove a panel from the cold box and begin the gravelometer test. Once cooled, the upper half of the panels was impinged with 1 pint of gravel (between 3/8 and 5/8 inch in size) projected at a pressure of  $70 \pm 3$  pounds per square inch (psi). The tops of the panels were then evaluated according to the rating specified in ASTM D 3170.

Next, the panels were placed in the Harshaw salt fog cabinet (ASTM B 117, "Standard method of salt spray (fog) testing") for a period of 500 hours. The panels rested on the racks with the impinged area at the bottom (Figure 1).




Figure 1. Rack in the Salt Spray Chamber

This prevented the rusting steel (exposed due to impingement) from draining down the panel. This also prevented moisture from penetrating underneath the topcoat and damaging the lower section of the panel. Upon completion of the salt fog exposure, the top and bottom of the panels were evaluated separately according to ASTM D 1654, "Standard method for evaluation of painted or coated specimens subjected to corrosive environments." After the evaluation, the panels were cooled again, then hit with gravel on the lower half. The final step in the testing was the ASTM D 3170 rating of the lower section.

Based on the ASTM D 1654 and D 3170 evaluations, the performance of the rust converters is shown below and graphed in Figures 2 and 3, respectively:

#### Laboratory pre-corroded panels

- 1. Commercial #2
- 2. Commercial #3
- 3. No rust converter
- 4. Commercial #1
- 5. Commercial #4

#### Fielded pre-corroded panels

- 1. No rust converter
- 2. Commercial #1
- 3. Commercial #2
- 4. Commercial #4
- 5. Commercial #3




Figure 2. Cyclic Gravelometer/Salt Spray-Laboratory Pre-corrosion




Figure 3. Cyclic Gravelometer/Salt Spray -Field Pre-corrosion

210 KKKKKKI CSSSSSIFIK CKKKKKK CKKKKI OKKKKKKKKI OKKKKI OKKKKK (KKSSSKOS) (STSZSFA (ISSSANA) DOSÉ

It is easily noticeable that the cyclic gravelometer/salt spray testing produced different results when tested on field and salt spray pre-corroded panels. Neither the bituminous coating (no rust converter) nor any of the rust converters performed the same. Therefore, in this laboratory experiment, no correlation could be found between the laboratory pre-corroded panels and the field pre-corroded panels.

#### SECTION III. HUMIDITY

After the panels were prepared, they were placed in the humidity chamber and tested in accordance with ASTM D 2247, "Standard method for testing coated metal specimens at 100% relative humidity." The test ran in cycles consisting of 8 hours of condensation at 40°C, followed by 4 hours of dry off at 60°C. Upon completion of the 500 hour test, the panels were evaluated according to ASTM D 714, "Standard method of evaluating degree of blistering of paints," and ASTM D 1654, "Standard method for evaluation of painted or coated specimens subjected to corrosive environments."

The performance of the rust converters based on these evaluations is shown below and graphed in Figures 4 and 5, respectively.

# Laboratory pre-corroded panels

- 1. No rust converter
- 2. Commercial #2
- 3. Commercial #4
- 4. Commercial #1
- 5. Commercial #3

#### Fielded pre-corroded panels

- 1. No rust converter Commercial #4
- 3. Commercial #2
  Commercial #1
- 5. Commercial #3

Exposing both salt spray and field pre-corroded panels in the humidity chamber produced similar results. It is worth noting that the panels performed better when the intermediate step using the rust converter was eliminated, showing that the rust converters seem to promote accelerated corrosion, instead of retarding it.





Figure 4. Humidity—Laboratory Pre-corrosion

A TONDONO DE LOCALACA CARRACA CARRACA CONTRACA CARRACA CARRACA



opode sociolistica vientia destribes medicas sociolists destribe destribes sociolists desirates de la contrata del la contrata de la contrata del la contrata de la contrata de la contrata de la contrata de la contrata del la contrata de la contrata del la

Figure 5. Humidity—Field Pre-corrosion

# SECTION IV. REVERSE IMPACT RESISTANCE

Reverse impact resistance testing was carried out in accordance with Federal Test Method Standard (FTMS) 6226, "Impact resistance (reverse)." (NOTE: Subsequent to this testing, ASTM D 2794, "Standard test method for resistance of organic coatings to the effects of rapid deformation (impact)," replaced FTMS 6226.) Testing was performed using the G.E. Impact Tester. The impact weight shown in Figure 6 was dropped from a height of 2 feet.




Figure 6. Impact Weight


Four trials were performed on prepared and cured panels. Each trial consisted of two hits—one from side A and one from side B of the impact weight. Trial #1 was performed in the upper left-hand corner of the panels at room temperature  $(70^{\circ}F \pm 5^{\circ}F)$ . Upon test completion, each point of impact was evaluated on a pass/fail basis. Any sign of a crack in the coating or visible metal constituted a failing score.

Once trial #1 was completed, the panels were cooled to -30°F in the cold temperature chamber for a least 2 hours prior to conducting trial #2. This 10° decrease below the test temperature of -20°F allowed for the time it took to remove the panel from the chamber and perform the test. The two hits of trial #2 were then performed on the lower left-hand corner of the panel. Again, once testing was completed, each point of impact was evaluated on a pass/fail basis.

All test panels were then placed the salt fog cabinets for a 500-hour duration in accordance with ASTM B 117, "Standard method of salt spray (fog) testing." Once removed from the salt fog cabinets, trial #3 and trial #4 were performed on the right-hand side of the panel. These tests were the same as trials #1 and #2, respectively, except they were performed after the salt spray exposure and on the opposite side of the panel.


Shown is a ranking of the rust converters based on the percentage of points passing the test. This data is graphed in Figures 7 and 8, respectively.

BOSSESSE SEXESSES SECTION OF THE PROPERTY OF T



RUST CONVERTER

Figure 7. Reverse Impact Resistance—Laboratory Pre-corrosion



RUST CONVERTER

Figure 8. Reverse Impact Resistance... Field Pre-corrosion

Paradian Seese Manager I

#### Laboratory pre-corroded panels

- 1. Commercial #1
- 2. Commercial #2
- 3. Commercial #4
- 4. Commercial #3
- 5. No rust converter

#### Fielded pre-corroded panels

- 1. Commercial #3
- 2. Commercial #1 Commercial #2
- 4. No rust converter Commercial #4

In this comparison, Commercial #3 showed a drastic difference in performance when tested over field pre-corrosion and laboratory pre-corrosion in the salt spray. It appeared to last longer than the others over the uniform corrosion found in the field. Note the alteration of Commercial #1's performance—when it converted laboratory pre-corrosion, it clearly out-performed Commercial #2; but over field pre-corrosion, its performance only equaled that of Commercial #2. Taking these differences into consideration, the reverse impact resistance tests yielded no similarities when performed on laboratory and field pre-corrosion.

#### SECTION V. FLORIDA TESTING

Testing in Florida was carried out in conjunction with the gravelometer test. The procedures followed in the cyclic gravelometer/salt spray test were similar to those followed in the laboratory with the following exceptions: the exposure was in Florida rather than the salt fog cabinet, and the rust converter, Commercial #4, was not evaluated in Florida.

As with the cyclic gravelometer/salt spray testing, the panels for the Florida exposures were prepared, cured, and cooled to 10° below the test temperature of -20°F to allow for a 10-second warm up period from the cold temperature chamber to the gravelometer. Once the panels reached equilibrium in the cold temperature chamber, the upper half was impinged in the gravelometer according to ASTM D 3170, "Standard test method for chip resistance of coatings." The panels were then evaluated using the same standard. (NOTE: A period of 2 hours was arbitrarily decided upon. ASTM D 3170 recommended at least 1 hour in the cold temperature chamber for the panels to reach equilibrium.)

Following the above procedure, the panels were exposed by Sub-Tropical Testing Service in Miami, Florida. The panels were placed at a 45° angle from the horizontal facing south. They were placed in the racks so the impinged area was at the bottom (refer to Figure 1). This prevented drainage from running down the panel, penetrating underneath the topcoat, and thus damaging the unimpinged lower section.

After a period of 12 months, the top and bottom of the panels were evaluated according to ASTM D 610, "Standard method of evaluating degree of rusting of painted steel surfaces," ASTM D 714, "Standard method of evaluating degree of blistering of paints," and ASTM D 1654, "Standard method for evaluation of painted or coated specimens subjected to corrosive environments." Next, the panels were cooled and impinged with gravel on the lower half. In the final step, the lower section was evaluated according to ASTM D 3170.

Considering the ASTM standard evaluations previously stated, the resulting rust converter performances are shown below and graphed in Figures 9 and 10, respectively.

#### Laboratory pre-corroded panels

- 1. No rust converter Commercial #1
- 3. Commercial #2
- 4. Commercial #3

# Fielded pre-corroded panels

- 1. No rust converter
- 2. Commercial #2
- 3. Commercial #1
- 4. Commercial #3

These results show some similarity. Commercial #1's performance was clearly affected by the pre-corrosion method. It seemed to do much better in this experiment on laboratory pre-corrosion. Note that the field pre-corroded panels performed better when the intermediate step using the rust converter was eliminated. This would indicate that the rust evonverters promote corrosion after a period of exposure. Due to economic considerations, the laboratory pre-corroded panels not treated with the rust converter prevailed. The extra expense of using the rust converter was not justified to produce the same results as if it were not used. Except for the difference in the Commercial #1 performance, the Florida testing appeared to produce similar results when testing laboratory and field pre-corroded panels.





Figure 9. Horida Testing-Laboratory Pre-corrosion



RUST CONVERTER

Figure 10. Florida Testing-Field Pre-corrosion

n experience in recommendation of the consideration of the contens of the contens of the contens of the contens of

Okstratismo.

# SECTION VI. FIELD EXPOSURE

Field exposure was conducted in three separate locations: Florida, Hawaii, and Puerto Rico. The exposure in Florida was conducted by Sub-Tropical Testing Service of Miami, Florida. (See Section V.)

The Hawaii and Puerto Rico panels were prepared in the same manner as previous testing discussed in this report. However, unlike previous testing, all panels exposed were pre-corroded for 24 hours in the salt fog cabinets according to ASTM B 117, "Method of salt spray (fog) testing." Field pre-corroded and 120-hour salt spray pre-corroded panels were not considered in Florida. The following rust converters were evaluated:

#### Hawaii exposure

- 1. Commercial #3 (annic acid based with latex)
- 2. Commercial #5 (tannic acid based with latex)
- 3. Commercial #6 (phosphoric acid based)
- 4. Commercial #7 (phosphoric acid based)

#### Puerto Rico exposure

- 1. Commercial #4 (tannic acid based with latex)
- 2. Commercial #2 (tannic acid based)
- 3. Commercial #7 (phosphoric acid based)
- 4. Commercial #3 (tannic acid based with latex)
- 5. Commercial #6 (phosphoric acid based)
- 6. Commercial #5 (tannic acid based with latex)
- 7. Commercial #8 (tannic acid based with latex)

The panels were oriented at a 45° angle from the horizontal facing south. After a duration of 12 months of exposure in their respective locations, the panels were evaluated according to ASTM D 610, "Standard method of evaluating degree of rusting of painted steel surfaces," ASTM D 714, "Standard method of evaluating degree of blistering of paints," and ASTM D 1654, "Standard method for evaluation of painted or coated specimens subjected to corrosive environments."

According to these ASTM standard evaluations, the resulting rust converter performances are shown below:

# Hawaii exposure

- 1. Commercial #7
- 2. Commercial #3
- 3. Commercial #5
- 4. Commercial #6

#### Puerto Rico exposure

- 1. Commercial #2
  No rust converter
  Commercial #4
- 4. Commercial #7
- 5. Commercial #6
- 6. Commercial #3
- 7. Commercial #5
- 8. Commercial #8

None of the rust converters passed in the Hawaii experiment. A passing mark which was established in previous testing meant receiving a rating of three or better in the ASTM D 610 and ASTM D 1654 standards. Much of the bituminous coating covering the panels had flaked off, exposing the metal surface below.

The information obtained from the Hawaii exposure was disregarded because the panels were lost in transit from Hawaii to Fort Belvoir for a period of time. The duration of the shipment was approximately 4 months. This is significant considering that the wooden boxes used to transport the panels would have become humidity chambers building excessive amounts of heat and moisture. Subsequently, the moisture penetrating underneath the bituminous coating would spread, thus corroding the panels and lifting up the remaining coating.

Therefore, since the Hawaii information has been disregarded, only a comparison between Florida and Puerto Rico exposures can be made. Because only laboratory precorrosion was tested in Puerto Rico, it will only be considered against the laboratory pre-corrosion results of the Florida exposure. These results are shown below for the sake of convenience:

Florida exposure (laboratory pre-corroded panels)

- 1. No rust converter Commercial #1
- 3. Commercial #2
- 4. Commercial #3

In the Florida exposure, the phosphoric acid based rust converter, Commercial #1, did much better than the tannic acid based, Commercial #2. This was not the case, however, in the Puerto Rico exposure. The tannic acid based rust converters, namely, Commercial #2 and Commercial #4, performed better than the phosphoric acid based rust converters, Commercial #7 and Commercial #6. Due to this inconsistency, no real similarity in the two exposures could be found.

#### SECTION VII. CONCLUSIONS AND RECOMMENDATIONS

The evaluations discussed in this report were undertaken in order to develop a rust converter suitable for military applications. Each particular experiment was performed on both laboratory and field pre-corrosion. The humidity test and the Florida exposure were the only evaluations in which the performances of the rust converters remained the same for both of these pre-corrosion techniques. In all of the remaining evaluations, the performance of the rust converters depended upon the type of pre-corrosion. The pre-corrosion produced in the salt spray chamber was different from that which occurred in the field. The field pre-corrosion was more uniform and showed no streaks as the salt sprayed panels did when the salt water accumulated and ran down the panel. The results from this experimentation showed that the salt spray should not be used as a pre-corrosion technique. Therefore, more time and effort must be placed on developing a pre-corrosion technique which cycles between wet and dry periods, while introducing other parameters, such as ultraviolet light found in the field.

Evaluations on the panels also determined that the currently available rust converters actually accelerated corrosion after a period of time. The majority of the results proved that the bituminous coating directly over the pre-corrosion performed better than using the rust converter as an intermediate step. More research will be needed to formulate a rust converter with properties capable of withstanding harsh military environments.

#### **DISTRIBUTION FOR REPORT NO. 2457**

#### **PEPARTMENT OF DEFENSE**

- Director, Technical Information
   Defense Advanced Research Projects
   Agency
   1400 Wilson Blvd.
   Arlington, VA 22209
- DirectorDefense Nuclear AgencyATTN: TITLWashington, DC 20305
- 2 Defense Technical Information Center Cameron Station ATTN: DTIC-FDAC Alexandria, VA 22304-6145

#### DEPARTMENT OF THE ARMY

- 1 HQDA (DAMA-AOA-M) Washington, DC 20310
- 1 HQDA (DALO-TSM) Washington, DC 20310
- 1 HQDA (DAEN-RDL) Washington, DC 20314
- 1 HQDA (DAEN-MPE-T) Washington, DC 20314

el socioses terresces described trescentes assesses constite socioses terresces

- 1 Commander
  US Army Missile Research & Development
  Command
  ATTN: AMSMI-PR
  Redstone Arsenal, AL 35809
- Director
   Materials Technology Lab
   ATTN: AMXMR-RL Technical Library
   Watertown, MA 02172-0001
- Commander
   Chemical Research R&D Center
   ATTN: SMCCR-SPS (Tech Library)
   Aberdeen Prvng Ground, MD 21010-5423

- Commander
   US Army Aberdeen Proving Ground
   ATTN: STEAP-MT-U (GE Branch)
   Aberdeen Proving Ground, MD 21005
- Director
   US Army Materiel Systems
   Analysis Agency
   ATTN: AMXSY-MP
   Aberdeen Prvng Ground, MD 21005-5071
- 1 Director US Army Ballistics Research Laboratory ATTN: AMXBR-OD-ST (STINFO) Aberdeen Prvng Ground, MD 21005-5066
  - Director
    US Army Engineer Waterways
    Experiment Station
    ATTN: Chief, Library Branch
    Technical Information Center
    Vicksburg, MS 39180
- 1 Commander
  US Army Armament Research &
  Development Command
  ATTN: SMCAR-TSS
  Dover, NJ 07801-5001
- 1 Commander
  US Army Troop Support & Aviation
  Materiel Readiness Command
  ATTN: DRSTS-MES (1)
  4300 Goodfellow Blvd.
  St. Louis, MO 63120
- 2 Director Petrol & Fld Svc Dept US Army Quartermaster School Fort Lee, VA 23801
- 1 US Army Tank Automotive Command ATTN: DRSTA-TSL Warren, MI 48090
- 1 U S Army Laboratory Command ATTN: M. Levy SLCMT-MM Materials Technology Laboratory Watertown, MA 02172-0001

- US Army Laboratory Command ATTN: J. Wells SLCMT-MCZ Materials Technology Laboratory Watertown, MA 02172-0001
- 1 Commander
  US Army Electronics Research &
  Development Command
  ATTN: DELSD-L
  Fort Monmouth, NJ 07703-5301
- 1 President
  US Army Aviation Test Board
  ATTN: STEBG-PO
  Fort Rucker, AL 36360
- US Army Aviation School Library PO Drawar O
   Fort Rucker, AL 36360
- 1 HQ 193D Infantry Brigade (Pan) ATTN: AFZU-FE APO Miami 34004
- Special Forces Detachment, Europe ATTN: PBO APO New York 09050
- 2 Engineer Representative
  USA Research & Standardization
  Group (Europe)
  Box 65
  FPO 09510
- Commander
  Rock Island Arsenal
  ATTN: SARRI-LPL
  Rock Island, IL 61299-7300
- 1 HQDA
  ODCSLOG
  DALO-TSE
  Room 1E588, Pentagon
  Washington, DC 20310-0561
- 1 Plastics Technical Evaluation Center ARRADCOM, Bldg 3401 Dover, NJ 07801
- 1 Commandant
  US Army Engineer School
  ATZA-CDD
  Fort Belvoir, VA 22060

- US Army AMCCOM ATTN: Joseph Menke
   1032 N. Thornwood
   Davenport, IA 52804
- 1 Commander
  US Army Electronics Research &
  Development Command
  ATTN: DELSD-L
  Fort Monmouth, NJ 07703-5301
- 1 President
  US Army Aviation Test Board
  ATTN: STEBG-PO
  Fort Rucker, AL 36360
- US Army Aviation School Library PO Drawar O
   Fort Rucker, AL 36360
- 1 HQ 193D Infantry Brigade (Pan) ATTN: AFZU-FE APO Miami 34004
- Special Forces Detachment, Europe ATTN: PBO APO New York 09050
- Engineer Representative
   USA Research & Standardization
   Group (Europe)
   Box 65
   FPO 09510
- 1 Commander
  Rock Island Arsenal
  ATTN: SARRI-LPL
  Rock Island, IL 61299-7300
- 1 HQDA
  ODCSLOG
  DALO-TSE
  Room 1E588, Pentagon
  Washington, DC 20310-0561
- Plastics Technical Evaluation Center ARRADCOM. Bldg 3401 Dover, NJ 07801
- 1 Commandant
  US Army Engineer School
  ATZA-CDD
  Fort Belvoir, VA 22060

#### 1 President

US Army Airborne, Communications & Electronics ATTN: STEBF-ABTD Fort Bragg, NC 28307

1 Commander
Headquarters, 39th Engineer Battalion
(Cbt)
Fort Devens, MA 01433

President
US Army Armor and Engineer Board
ATTN: ATZK-AE-PD-E
Fort Knox, KY 40121

1 Commander and Director
USA FESA
ATTN: FESA-TS
Fort Belvoir, VA 22060

1 HW, USAEUR & Seventh Army Deputy Chief of Staff, Engineer ATTN: AEAEN-MT-P APO New York 09403

Director
 US Army TRADOC
 Systems Analysis Activity
 ATTN: ATAA-SL (Tech Lib)
 White Sands Missile Range, NM 88002

#### 1 BELVOIR RD&E CENTER

Commander STRBE-Z
Deputy Commander STRBE-ZD
Technical Director STRBE-ZT
Assoc Tech Dir (E&A) STRBE-ZTE
Assoc Tech Dir (R&D) STRBE-ZTR
Executive Officer STRBE-ZX
Sergeant Major STRBE-ZM
Advanced Systems Concept Dir STRBE-H
Program Planning Div STRBE-HP
Foreign Intelligence Div STRBE-HF
Systems and Concepts Div STRBE-HC
CIRCULATE

- 1 STRBE-V
- 30 STRBE-VC
- 3 Tech Reports Ofc STRBE-BPG
- 3 Security Ofc (for liaison officers) STRBE-S
- 2 Tech Library STRBE-BT
- 1 Publics Affairs Ofc STRBE-I
- 1 Ofc of Chief Counsel STRBE-L

# DEPARTMENT OF THE NAVY

1 Director, Physics Program (421) Office of Naval Research Arlington, VA 22217

1 US Naval Oceanographic Office Navy Library/NSTL Station Bay St. Louis, MO 39522

Library (Code L08A)
 Civil Engineering Laboratory
 Naval Construction Battalion Center
 Port Hueneme, CA 93043

Director
Earth Physics Program
Code 464
Office of Naval Research
Arlington, VA 22217

 Naval Training Equipment Center ATTN: Technical Library Orlando, FL 32813

Naval Sea Systems Command ATTN: P. Schneider PMS377J1 Washington, D C 20362-5101

 Naval Air Development Center ATTN: V.S. Agarwala, Code 6062 Warminster, PA 18974

#### DEPARTMENT OF THE AIR FORCE

- 1 HQ USAF/RDPT ATTN: Commander Washington, DC 20330
- 1 HQ USAF/PREEU Chief, Utilities Branch Washington, DC 20330
- 1 US Air Force HQ Air Force Engineering & Service Ctr Technical Library FL7050 Tyndall AFB, FL 32403
- US Air Force
   Warner Robins Air Logistics Center
   WR-ALC/MMEM
   Warner Robins AFB, Georgia 31098
- 1 Chief, Lubrication Br Fuels & Lubrication Div ATTN: AFWAL/POSL 800 Independence Ave., SW Washington, DC 20591